

Customer Name: Robertson	Date: 08/02/23
Customer Reference: 7730	Fitter: Gary
Salesperson: Gary	Salesperson called: Yes/No No
Blind Type and number: Shutter	
Fault Description: Wood at top left	
Action to correct: Order new left leg for lounge shutter with 4 panels 1156mm	
Problem fixed on site: No	
Further action required:	

Fault Report