

Customer Name: Burns	Date: 28/05/23
Customer Reference: 8067	Fitter: Gary
Salesperson: Gary	Salesperson called: Yes/No
Blind Type and number: Track	
Fault Description: Track in lounge. Track in lounge had no runners or brackets	
Action to correct: Going back to fit remainin	
Problem fixed on site: Y	
Further action required: No	

# Fault Report