

RAIN 8016
ALEXANDER/R

Fault Report

Customer Name: ALEXANDER	Date: 10-6-24
Customer Reference: 8016	Fitter: GRAEME
Salesperson: GARY.	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: ALL BLINDS BAR 1 NEED RE MADE.	
Fault Description: MEASUREMENTS FOR INSIDE RECESS SHOULD BE OUTSIDE DUE TO TILT + TURN WINDOWS.	
Action to correct: REMOVE BLINDS.	
Problem fixed on site: Yes/No	
Further action required:	

lower ADJUST BODEN BALK L 1790. ✓
R 1790 ✓ ~~1790~~ BIA.

To them 1790 EXTRA BAK. ✓

PURPOSE 2515 x 2110 FABRIC.

~~1790~~ ^{DUAL} BATH 1690 x 1260 ✓

FRED R 1690 x 1365 ✓

JOURNAL 860 x 1110. ✓

FRED L 1700 x 1360 ✓

BATH ~~1700~~ 1020 x 1060. ✓

BBED R 1700 x 1265. ✓

BBED LR 1700 x 1365 ✓

EVSONS 1020. x 1060. ✓

KIRK L 1360 x 1310 ✓

R 1360 x 1140. ✓