

SB16236R

RAIN 8661
NEWBURY/R

Customer Name: Newberry	Date: 20/12/24
Customer Reference: 8661	Fitter: Gary
Salesperson: Gary	Salesperson called: No
Blind Type and number: Velux	
Fault Description: Side channels and cords too long	
Action to correct: Reorder. Should be GPL M08	
Problem fixed on site:	
Further action required:	

Fault Report

