

**ABERDEEN  
BLIND COMPANY**  
ESTABLISHED 1952

32 Esslemont Avenue  
Aberdeen  
AB25 1SP  
Tel: 01224 637609  
Fax: 01224 631172  
Email: sales@aberdeen-blinds.co.uk

37107

Rutherford 27/2  
37107A  
1 x H/R  
(re-make)

(M)	P/CUST
	NET
	PRESS
	RADIO
	MAG.
	VAN
	RECC.
	SHOP
	TV
	YELL P
	OTHER

Customer's Name Rutherford  
Address 65 Simpson Road  
Bridge of Don  
AB23 Post Code 8HL

DATE  
MEASURED/ORDERED  
01 / 02 / 19

CURTAINS	
PLEATED	
ROLLERS	
ROMANS	
SHUTTERS	
VENETIAN	✓ XI
VERTICALS	
VISION	
WOODEN	

Tel. home	01224 822438
Tel. work	
mobile	
email	

**ALL BLINDS TO BE PAID FOR AT TIME OF FITTING**

Room	No.	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Any other Instructions	Price
BED		38 60	9 78	89	WARWICK	RH	2400	SPLIT	238
		33 50	Exact		WHITE 'A				
					FACE FIX TO TOP OF				
					DARK WOOD.				
					HEAD RAIL				
					TOO LONG				

alum	white	brown	white chain	welded in weight	recess size	window not square	wood fix	stone fix	brackets top	face
	✓			✓	✓	✓	✓			✓

measured by	date	fitted by	date	CASH	CHEQUE	SPREE
COUD	1/2/19			INVOICE	CARD	

ALL BLINDS MANUFACTURED AFTER 1<sup>ST</sup> APRIL 2014 MUST COMPLY WITH NEW CHILD SAFETY LAWS. SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. REFUSAL TO ALLOW SAFETY DEVICE TO BE FITTED WILL RESULT IN THE BLINDS NOT BEING INSTALLED. UNDER THE TERMS OF THIS CONTRACT YOU WILL BE LIABLE TO ACCEPT DELIVERY AND PAY THE FULL AMOUNT. I have ordered the above goods and agree to pay the amount shown in full at the time of fitting. If payment is not made in full at that time Aberdeen Blind Company Ltd has the right to remove the goods until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE	£ 238	To Be Confirmed SAFE
DEPOSIT	£ 88	
BALANCE	£ 150	
		PRICE ACCEPTANCE Customer's Signature

Special Instructions  
\* FITTER - SCREW SAFETY INTO WALL  
- CONCRETE WALLS - ENSURE SCREW  
NOT TOO LONG SO DOES NOT HIT  
CONCRETE

M. Rutherford

MLL 11/2