

ABERDEEN BLIND COMPANY

ESTABLISHED 1952

32 Esslemont Avenue

Aberdeen

AB25 1SP

Tel: 01224 637609

Fax: 01224 631172

Email: sales@aberdeen-blinds.co.uk

38474

CUSTOMER ORDER No.

OK mjt

Customer's Name

O'Donnell

Address

99 Hamilton Place

Post Code

AB15 5BD

Tel. home	
Tel. work	
mobile	07702704681
email	

DATE MEASURED/ORDERED
12/8/19

CURTAINS	
PLEATED	
ROLLERS	✓ x3
ROMANS	
SHUTTERS	
VENETIAN	
VERTICALS	
VISION	
WOODEN	

AM PM (MEASURING TIME)	
MON	✓
TUE	
WED	
THU	
FRI	

AM PM (FITTING TIME)	
MON	
TUE	
WED	
THU	
FRI	

P/CUST	
NET	
PRESS	
RADIO	
MAG.	
VAN	
RECC.	
SHOP	
TV	
YELL P	
OTHER	

ALL BLINDS TO BE PAID FOR AT TIME OF FITTING

Room	No.	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Any other Instructions	Price
LOUNGE		6 10	22 80	Roll	GEMINI	LH	2300	FACE WOOD	131
Boys Window		11 60	1 1	"	B/O	RH		CURTAIN	187
Window		6 05	1 1	"	WYNN	RH		CURTAIN	131
									449

alum	white	brown	white chain	welded in weight	recess size	motorised	wood fix	stone fix	brackets top	brackets face
					✓		✓			✓

measured by	date	fitted by	date	CASH	CHEQUE	SPREE
DAVID	12/8/19			INVOICE	CARD	

ALL BLINDS MANUFACTURED AFTER 1ST APRIL 2014 MUST COMPLY WITH NEW CHILD SAFETY LAWS. SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. REFUSAL TO ALLOW A SAFETY DEVICE TO BE FITTED WILL RESULT IN THE BLINDS NOT BEING INSTALLED. UNDER THE TERMS OF THIS CONTRACT YOU WILL BE LIABLE TO ACCEPT DELIVERY AND PAY THE FULL AMOUNT. I have ordered the above goods and agree to pay the amount shown in full at the time of fitting. If payment is not made in full at that time Aberdeen Blind Company Ltd has the right to remove the goods until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE £ 449

To Be Confirmed
SALE

DEPOSIT £ 90

PRICE ACCEPTANCE
Customer's Signature

BALANCE £ 359

O'Donnell

Special Instructions
FIT DIRECTLY UNDER PLEATED WOOD. CURTAIN TRACK + PELMET NEED REMOVED
BRACKET
WOOD FACING