

ABERDEEN BLIND COMPANY

ESTABLISHED 1952

32 Esslemont Avenue
Aberdeen
AB25 1SP

Tel: 01224 637609
Fax: 01224 631172

Email: sales@aberdeen-blinds.co.uk

39174

CUSTOMER ORDER No.

TRX 14/11/19

Customer's Name Gordon
Address 56 Hamilton
place, Blantyre House
AB15 Post Code 43H

Tel. home	
Tel. work	
mobile	07768744055
email	

DATE MEASURED/ORDERED	13/11/19
-----------------------	----------

CURTAINS	
PLEATED	
ROLLERS	✓ x3
ROMANS	
SHUTTERS	
VENETIAN	
VERTICALS	
VISION	
WOODEN	

AM PM (MEASURING TIME)			P/CUST
MON			NET
TUE			PRESS
WED		✓ Evening	RADIO
THU			MAG.
FRI			VAN
AM PM (FITTING TIME)			RECC.
MON			SHOP
TUE			TV
WED			YELL P
THU			OTHER
FRI			

ALL BLINDS TO BE PAID FOR AT TIME OF FITTING

Room	No.	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Any other Instructions	Price
ROUWE		5 50	22 27	Roller	REV.	LH	3200	TOP/WOOD	109
RAY		11 96	" "	"	"	RH	"	* SEE BELOW	199
WINDOW		5 50	" "	"	"	RH	11		109
								SECURITY OFF WHITE P	417
								* LANDOZ TO 3.2 M	
								FITTING HEIGHT	

alum	white	brown	white chain	welded in weight	recess size	motorised	wood fix	stone fix	brackets top	brackets face
							✓		✓	

measured by	date	fitted by	date	CASH	CHEQUE	SPREE
DAVID	13/11/19			INVOICE	CARD	

ALL BLINDS MANUFACTURED AFTER 1ST APRIL 2014 MUST COMPLY WITH NEW CHILD SAFETY LAWS. SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. REFUSAL TO ALLOW A SAFETY DEVICE TO BE FITTED WILL RESULT IN THE BLINDS NOT BEING INSTALLED. UNDER THE TERMS OF THIS CONTRACT YOU WILL BE LIABLE TO ACCEPT DELIVERY AND PAY THE FULL AMOUNT. I have ordered the above goods and agree to pay the amount shown in full at the time of fitting. If payment is not made in full at that time Aberdeen Blind Company Ltd has the right to remove the goods until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE £ 417

DEPOSIT £ 100

BALANCE £ 317

To Be Confirmed

PRICE ACCEPTANCE

Customer's Signature

Special Instructions

* TOP FIX - WOOD, FRONT OF BRACKET AT FRONT OF RECESS - CEILING BLIND MAY HIT FITTINGS WHEN LOWERED - HOWEVER BRACKETS MUST NOT PROTRUDE BEYOND RECESS

Gordon