

# ABERDEEN BLIND COMPANY

ESTABLISHED 1952

32 Esslemont Avenue  
Aberdeen  
AB25 1SP  
Tel: 01224 637609  
Email: sales@aberdeen-blinds.co.uk

49020

**CUSTOMER  
ORDER No.**

Customer's Name Grant  
Address 9 ash row,  
balmedie  
Post Code AB23  
8SU

Tel. home	
Tel. work	
mobile	07875754218
email	

DATE MEASURED/ORDERED	
	10/9/12

CURTAINS		
PLEATED		
ROLLERS	✓	PE
ROMANS		
SHUTTERS		2/3
VENETIAN		
VERTICALS		
VISION	✓	
WOODEN		

		AM PM (MEASURING TIME)		P/CUST
MON				NET
TUE	✓			PRESS
WED				RADIO
THU				MAG.
FRI				VAN
		AM PM (FITTING TIME)		RECC.
MON				SHOP
TUE				TV
WED				YELL P
THU				OTHER
FRI				

## Balance for order payable on arrangement of installation

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Any other Instructions	Price
Kitchen L	414	778	PF 25	0150	L	22mm		178
R	415	778	PF 25	0150	R	22mm		178
								356
							-20%	284
Bedroom	1725	1115	VISION	Prima Frost	R	2060		475
				TOP WHITE CASSETTE				
				BOTTOM BAR				
							-20%	380
							TOTAL	664

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top	brackets face
								✓			✓	✓	

measured by	fitted by	date	CASH	CHEQUE	SPREE
DAVID H			INVOICE	CARD	

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. REFUSAL TO ALLOW A SAFETY DEVICE TO BE FITTED WILL RESULT IN THE BLINDS NOT BEING INSTALLED. UNDER THE TERMS OF THIS CONTRACT, YOU WILL BE LIABLE TO ACCEPT DELIVERY AND PAY THE FULL AMOUNT. I have ordered the above goods and agree to pay a 50% deposit and the remaining balance when confirming the installation appointment. If payment is not made in full at that time, Aberdeen Blinds have the right to refuse to install the products until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE £

DEPOSIT £

BALANCE £

**To Be Confirmed**

PRICE ACCEPTANCE  
Customer's Signature

Special Instructions

REMOVE EXIST  
AB23 8SU