

Fault Report

Customer Name: MOORE	Date: 21/1
Customer Reference: 51184	Fitter: AMO
Salesperson:	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Blind Type and number: WOODEN VENETIAN (2) 1160 X 2045	
Fault Description: Pics in box 1 X BLIND TOO SHORT. ALL SHOULD BE SAME DROP. 2045.	
Action to correct: New Blind	