

Fault Report

Customer Name: LYNDIA CLARK	Date: 13/03/2026
Customer Reference: S1553	Fitter: GREG WILKINSON
Salesperson: BILL CLARK	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: ROLLER.	
Fault Description: MEASURE TOO WIDE By 20mm WIDTH WAS 2110 SHOULD BE 2090	
Action to correct: To be CUT DOWN By 20mm. IF POSSIBLE.	

ABERDEEN BLIND COMPANY

ESTABLISHED 1952

32 Esslemont Avenue
Aberdeen
AB25 1SP
Tel: 01224 637609
Email: sales@aberdeen-
blinds.co.uk

51553

CUSTOMER
ORDER No.

Customer's Name **LYNDA CLARK**
Address **84 ASH GROVE ROAD WEST
ABDN**
Post Code **AB16 5EE**

Tel home
Tel work
mobile **07713 482029**
email

DATE
MEASURED/ORDERED
16/02/26

CURTAINS
PLEATED
ROLLERS
ROMANS
SHUTTERS
VENETIAN
VERTICALS
VISION
WOODEN

AM PM (MEASURING TIME)
MON
TUE
WED
THU
FRI

AM PM (FITTING TIME)
MON
TUE
WED
THU
FRI

PICUST
NET
PRESS
RADIO
MAG.
VAN
RECC.
SHOP
TV
YELL P
OTHER

Balance for order payable on arrangement of installation

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Any other instructions	Price
KITCHEN	2110	1200		ASPEN PLATINUM	LH	21SD	FACE FIT.	297
				CHROME CHAIN				
				Fabric Size Silver exposed				
				FAULT TOO LONG - BRACKET EXCEEDS WOOD FRAME. 20mm TOO WIDE				
				*2090	1200	IF FABRIC SIZE (EXACT)		
				2120	RECESS SIZE	BUT STILL FACE FIX		
							-10%	297

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top	brackets face
					<input checked="" type="checkbox"/>					<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>

measured by	fitted by	date	CASH	CHEQUE	SPREE
Bill Clark			INVOICE	CARD	

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. REFUSAL TO ALLOW A SAFETY DEVICE TO BE FITTED WILL RESULT IN THE BLINDS NOT BEING INSTALLED. UNDER THE TERMS OF THIS CONTRACT, YOU WILL BE LIABLE TO ACCEPT DELIVERY AND PAY THE FULL AMOUNT. I have ordered the above goods and agree to pay a 50% deposit and the remaining balance when confirming the installation appointment. If payment is not made in full at that time, Aberdeen Blinds have the right to refuse to install the products until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE £ **268.00**
DEPOSIT £ **134.00**
BALANCE £ **134.00**

To Be Confirmed
PRICE ACCEPTANCE
Customer's Signature

Special Instructions

Lynda Clark

SHOP OPEN Mon-Fri 8 - 5

VAT Reg No. 265 3431 64

Registered No.: 130460