

Fault Report

Customer Name: Oveo Arup	Date: 12.08.22
Customer Reference: 334205	Fitter: Scott Johnson
Salesperson: RD	Salesperson called: No
Blind Type and number: Roller	
Fault Description: This needs 2 men with extension ladders. We need to take chain and controls.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Rebook appointment with the above requirements. Booked in Thu 8/9 9am-12pm (Craig & Scott)	