

\*Ordered\*

G 348688 Barber/R1

Customer Name: Mrs Barber	Date: 2/12/21
Customer Reference: G 348688	Fitter: adam
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: PF roller	
Fault Description:  Perfect fit is not wide enough And did not sit right in the frame, tried moving the brackets out a little to hold the frame in place but the PF felt loose	
Action to correct: Order new PF 505by1855 505by1855	
Problem fixed on site: Yes/No	
Further action required:  Note the main reason why the blind did not fit was because the roller holder at the top was sitting on the frame and pushing it self out	