

S 351778

Baker IR.

Fault Report

Customer Name: Baker	Date: 04.04.22
Customer Reference: 351778	Fitter: Craig
Salesperson: Shaun	Salesperson called: Yes/No
Blind Type and number: B, fold doors (Kitchen) into Pleated	
Fault Description: Brackets not holding in rubbers correctly. Some have fallen out.	
Action to correct: replaced fallen brackets, explained to the customer an investigation will be opened into this case as its unusual.	
Problem fixed on site: Yes/No	
Further action required: needs discussed with Josh.	