

G 349467
McKeough/R

Fault Report

Customer Name: McKeough	Date: 7/12/21
Customer Reference:	Filter: CRACK M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: Roller 349467	
Fault Description: Barrell clamps missing from Guide Wires all components are on site	
Action to correct: Take Barrell clamps	
Problem fixed on site: Yes/No <input checked="" type="radio"/> No	
Further action required:	