

S 351430
Carr / R.

Fault Report

Customer Name: Carr	Date: 15.12.21
Customer Reference: 351430	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes/No
Blind Type and number: Infusion Wood, Blind 1 (Play Room)	
Fault Description: Blind fabricated too wide, it was measured correctly and also has correct size on the box.	
Action to correct: needs returned to the factory	
S/B 1723 x 1263	
Problem fixed on site: Yes/No	
Further action required: will be left in the unit on the 16.12.21.	