

BAILEYS - S'MOOR

S 351651

Jennings/R

Fault Report

Customer Name: JENNINGS	Date: 17-01-22
Customer Reference: 351651	Filter:
Salesperson: SHAUN H	Salesperson called: <input checked="" type="radio"/> Yes/ <input type="radio"/> No
Blind Type and number: 1x INFUSION WOOD BLIND (BED)	
Fault Description: SLATS WARPED - BOWING IN MIDDLE	
Action to correct: REPLACE BLIND WITH NEW ONE FRONT BED 175B x 1417 URBAN RADIANCE WHITE 1/R STD CTRLS F/A 2600	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: AS ABOVE	