

G 352199
McCluskey IR

Fault Report

Customer Name: McCluskey	Date: 31.03.22
Customer Reference: 352199	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes (No)
Blind Type and number: Curtain Track (lounge)	
Fault Description: runner channel closed when forming the curve	
Action to correct: opened back out but doesn't run smoothly	
Problem fixed on site: Yes/No	
Further action required: New 1.5m track needs ordered ASAP, put straight on my job when delivered. (5 minute job) (Balance £90.00 still to pay)	