

G 352433

Stanger / R

Fault Report

Customer Name: Stanger	Date: 13.04.22
Customer Reference: 352433	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Blind 1 & 2 Verticals	
Fault Description: needs to be wand control as stated on order form	
Action to correct: N/A	
Problem fixed on site: Yes/No	
Further action required: New blinds (headrails) need ordered, Call customer to inform them of the new date. ASAP customer not happy.	

Office Error