

Fault Report

Customer Name: Wilkinson	Date: 05.04.24
Customer Reference: 350893	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Wood Venetian	
Fault Description: Cords on the up and down controls have started to unwind/fray.	
Action to correct: Graeme has images.	
Problem fixed on site: No	
Further action required: See Graeme.	

(11/4)
VM left to
advise customer
£80 call out
to collect blind
& £30 re-cord