

G 352559

Harrison. R.

Fault Report

Customer Name: Harrison	Date: 14.07.22
Customer Reference: 352559	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Curtain and Track	
Fault Description: Customer not happy with the track and how the pinched pleats lie on it, also overlap arm doesn't work with pinched pleat.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Resend Dave to discussed	
Dave Re-visiting	