

Fault Report

Customer Name: KITCHING	Date: 05/10/22
Customer Reference: 346085	Fitter:
Salesperson:	Salesperson called: Yes/No YES
Blind Type and number: 1 X VENETIAN INTU BLIND	
Fault Description: REPLACE BAKEN SLATS	
Action to correct: REPLACE SLATS	
Problem fixed on site: Yes/No YES	
Further action required: REPLACE SLATS & RETURN TO BAILEY TO REPT	