

G353091.

# Fault Report

Customer Name: SIMON CORRY	Date: 28/9/22
Customer Reference: 353091	Fitter:
Salesperson: DAVE	Salesperson called: Yes (No)
Blind Type and number: Roller 1 & 2	
Fault Description: BLINDS MADE INCORRECTLY	
Action to correct: NEW BLINDS REQUIRED (Dims correct but made too big).	
Problem fixed on site: Yes (No)	
Further action required: wayne sending back to be cut down.	