

S 350812

Garnett

Fault Report

Customer Name: GARNETT	Date: 03-10-22
Customer Reference: 350812	Fitter:
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTERS	
Fault Description: Both SHUTTERS wrong send Greame with me to adjust on site	
Action to correct: adjust SHUTTERS	
Problem fixed on site: Yes/No	
Further action required:	

BALLETTS - 5' MOOR

Shutter Survey Sheet

Number of Shutters: 2 Survey Date: 13/05/22 Customer Name: ERNETT Fitters Required: 1
 Survey Sheets: 1 Surveyor: SHAWN GERAHAN Order Number: 350812 Estimated Fit Time: 3 HRS

Item Number	1	2	3	4	5
Material:	NEW YDARK WOOD				
Colour:	002 WENET				
Room Name:	BED L	BED R			
Width:	833	835	* SEE BELOW		
Drop:	1445	1450			
Mounting Type:	FULL HEIGHT				
Panel Quantity:	LR	LR			
Louvre Size:	76	76			
Tilt Rod Type:	HIDDEN TILT				
Mid Rail:					
Louvre Split:	LR	LR			
Panel Configuration:	WHITE	WHITE			
Hinge Colour:	DEEP PLAIN L60				
Frame Type:	4	4			
No Of Sides:	AST	AST			
Style Type:					
Build Out:					
Extras:					
Further Instructions	* BOTH SHUTTERS ARE WITH				
Further Instructions	* ARCHED SHAPE SUN BRAST				

Panel Limitations (Single Panel / Bi Fold)	63mm	76mm	89mm	114mm
New York	850/650	850/650	850/650	850/650
Los Angeles PVC	900/650	900/650	900/650	900/650
New York Max Config	LLLLRRR			
Los Angeles PVC Max Config	LLRR			

Batten Sizes (W X D)	Length	Quantity

Order Information:

Deposit Paid: _____ Balance to Pay: _____

Customers Signature: _____ Date: _____

Surveyor Signature: _____ Date: _____



