

G 353153
Holmes/R

② Fault Report

Customer Name: Holmes

Customer Reference:

353153

Salesperson:

Date: 14/10/22

Fitter: WATRE

Salesperson called: Yes No

Blind Type and number: BLIND 1

Fault Description:

BLIND NOT WORKING CORRECTLY
STICKING WHEN IN USE

Action to correct:

NEW RAIL NEEDED

Problem fixed on site: Yes No

Further action required:

