

G348527

# Fault Report

|   |                        |
|---|------------------------|
| Customer Name: Lumsden  | Date: 18.10.22         |
| Customer Reference: 348527  | Fitter: Scott Johnson  |
| Salesperson: Dave   | Salesperson called: No |
| Blind Type and number: Vertical blind   |                        |
| Fault Description: Blind is damaged but too high to inspect as discussed may be worth ordering new headrail and booking a 2 man fit with extension ladders, they is also some vanes to rehang, can be done on the same visit. |                        |
| Action to correct: N/A  |                        |
| Problem fixed on site: No   |                        |
| Further action required: Order new headrail and book a 2 man fit with extension ladders.  |                        |