

G 353562

ARMSTRONG,

# Fault Report

Customer Name: Armstrong	Date: 17.01.23
Customer Reference: 353562	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Vertical, Bedroom	
Fault Description: Vertical curved track missing from order as discussed.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new headrail, vanes on site £148 to pay.  Collected from NSB + being <u>fitted</u> 20/1	