



G 352447
Irving IR.

③ Fault Report

Customer Name: <i>Irving</i>	Date: <i>2928/11/22</i>
Customer Reference: <i>352447</i>	Fitter: <i>Craig M</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>SHUTTER 2ND Landing</i>	
Fault Description: <i>customer now wants bottom of frame replacing as has small paint chips photo sent to nicole</i>	
Action to correct: <i>Must have been done after fit as weren't there when</i>  <i>1 fitted</i> <i>2ND Landing (replace)</i>	
Problem fixed on site: Yes/No	
Further action required:	

352447

② Fault Report

Customer Name: IRVING	Date: 27/8/22
Customer Reference: 352447	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTERS	
Fault Description: SHUTTER HAS SMALL INDENTATION ON BOTTOM OF FRAME CUSTOMER WANTS REPLACING ALSO WILL NEED COVERSTRIPS FOR SIDES (I HAVE 1 IN W/IN) Lounge = BOTTOM FRAME	
Action to correct:  Lounge SHUTTER ↑ BOTTOM FRAME MARKED.	
Problem fixed on site: Yes/No	
Further action required: ORDER BOTTOM OF FRAME	
29/11/22 - still to do + new fault report cm.	

352447

① Fault Report

Customer Name: 12ving	Date: 11/7/22
Customer Reference: 352447	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTERS	
Fault Description: Need to take out 2x door panel pins as missing	
Action to correct: Take out 2x door panel pins	
Problem fixed on site: Yes/No	
Further action required:	



34 HIGH STREET
SPENNYMOOR,
DURHAM DL16 8DD
TEL: 01388 81267 or 0191 268 5556
sales@baileysblinds.co.uk
www.baileys-blinds.co.uk

Customer's Name: IRVING
Address: 39 HOLYNELL AVENUE
WILTLEY BAY
Post Code: NE26 3AQ

DATE MEASURED/ORDERED
1/4/22

Measured By
DAVE

G352447

SPECIAL INSTRUCTIONS

MULTIFLEX ACCESS
FOR RAILS,
DINER @ PLATS
WHITE 22 BLADES
756 x 390 / 131 R
598 x 1100 / 150 R
£2531.00

PAYMENT
NET
PREPAY
RAILS
MAG
VAL
RECS
SHOP
IV
YELL P
OTHER

tel home
tel work
mobile: 07484 140578
email

COLOURS
PILARS
ROTTEN
ROBBER
SHUTTERS
VALVE HAN
MATERIALS
VEHICLE
WOODEN

2x Plats

Fitted By DATE DAY AM/PM

alum	anthracite	black	brown	champ gold	carbon	grey	white	brushed aluz	matronised	wood fl.	stone fl.	bracket top	bracket face
------	------------	-------	-------	------------	--------	------	-------	-----------------	------------	-------------	--------------	----------------	-----------------

room	Width	Depth	Stat Size	Color	Control Type	Fitting Height	Price
DINER ①	905	1985	70	NEW VOILE	MID DEPT 985	LL	626.00
DINER ②	1020	2700	+	NEW VOILE	985	LL	968.00
DINER ③	908	1976	-	NEW VOILE	985	RR	627.00
1/2 LAMP	1500	702	+	NEW VOILE	NO MID	RRR	369.00
LOWING	2300	1465	+	NEW VOILE	680	RRR	1179.00
2ND 1/2 LAMP	1510	1635	+	NEW VOILE	NO MID	RRR	865.00
BATTEN for BOTTOM 60 x 35 x 2300 of LOWING							40.00
6x SHUTTERS							TOTAL 4671.00

2x PLATS + 5x SHUTTERS - TOTAL 3989.00

Fit completed + Balance Paid. 11/07/22. cm
* Fault report - to follow *

SAFETY INSTRUCTIONS: FITTING AND USE OF BLINDS MUST BE ACCORDING TO THE INSTRUCTIONS PROVIDED WITH THE PRODUCT. TO ALLOW A QUALITY DEVICE TO BE FITTED, THEN THE GOODS WILL NOT BE INSTALLED AND USED IN THESE CIRCUMSTANCES, YOU WILL BE LIABLE TO PAY THE FULL PRICE UNDER YOUR CONTRACT. YOU WILL BE RESPONSIBLE TO SECURE USE AND FITTING OF THE GOODS AND TO PAY FOR THE FITTING AND INSTALLATION EVEN IF THE GOODS HAVE BEEN DAMAGED.

I have ordered the above goods and agree to pay 50% of the cost and the remaining balance from the day of fitting. If payment is not made in full at that time Baileys Blinds Ltd. the right to remove the goods and full settlement is reserved. Title of the goods does not pass to the customer until payment has been made in full. Excluding but these shall be no liability for normal damage or customer by or to be removed.

TOTAL PRICE: £3989.00
Pd 11/04/22 VISA DEPOSIT: £1994.50
BALANCE: £1994.50
PRICE ACCEPTANCE Customer's Signature: RAINBOW 187711 Go ANCAD

ALL BLINDS TO BE PAID FOR AT TIME OF FITTING



Pd 11/07/22 VISA

Q