

5354358 / R

Fault Report

Customer Name: OXLEY	Date: 17/01/23
Customer Reference: 354358	Fitter: SCOTT
Salesperson: SHAUN	Salesperson called: Yes/No
Blind Type and number: 1 X CURTAIN POLE	
Fault Description: WRONG FINIALS SUPPLIED	
Action to correct: SUPPLY CORRECT FINIALS	
Problem fixed on site: Yes/No	
Further action required: SUPPLY 2 X BROOKLYN STYLE CHROME FINIALS (28mm POLE) ON ORDER (BELGRAVIA WAS SUPPLIED - WRONG ONES.)	