

S 354614  
Leonard/R

# Fault Report

Customer Name: Leonard	Date: 06.04.23
Customer Reference: 354614	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Wood Venetian, Back Bed	
Fault Description: Blind damaged beyond repair please see images attached to email.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind.	
*Re-Ordered*	



S10



To avoid strangulation and entanglement, keep cords out of the reach of young children. Cords may become wrapped around child's neck.

inner cords that operate the product.

