

S 349952

Supportive SRC/R

Fault Report

Customer Name: Supportive SRC	Date: 06.04.23
Customer Reference: 349952	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Verticals	
Fault Description: Slats on blinds 2,3 & 4 were incorrect sizes and all slats should be without weights and chains. Blind 1 drop 1300mm, Blind 2 drop 1290mm, Blind 3 drop 1290mm, Blind 4 drop 1300mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new slats.	