

9348481

HEWITT

Fault Report

Customer Name: Hewitt	Date: 21.04.23
Customer Reference: 348481	Fitter: Scott Johnson
Salesperson: Craig M	Salesperson called: Yes
Blind Type and number: Wood venetian, Kitchen	
Fault Description: Pelmet should be left hand return.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new pelmet with LH return.	