

Q353828

RICKARD.

Fault Report

Customer Name: Rickard	Date: 23.05.23
Customer Reference: 353828	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised roller in cassette	
Fault Description: Blind fabricated incorrect size. Measured size is recess size.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind. <i>In unit to be collected.</i>	