

S354915
FINLAY/R.

Fault Report

Customer Name: FINLAY	Date: 26/06/23
Customer Reference: 354915	Fitter: CRAIG
Salesperson: SHAUN	Salesperson called: Yes/No
Blind Type and number: VERTICAL VANES	
Fault Description: 16 VANES MADE THE WRONG WIDTH (5")	
Action to correct: REMAKE 16 VANES AT CORRECT WIDTH OF 3 1/2 "	
Problem fixed on site: Yes/No	
Further action required:	