



S349965  
DAVINPORT

# Fault Report

Customer Name: DAVINPORT	Date: 06/07/23
Customer Reference: DH1 1DU	Fitter: CRAIG
Salesperson: SERVICE CALL	Salesperson called: Yes/No
Blind Type and number: ROMAN BLIND	
Fault Description: ROMAN BLIND MECHANISM (CONTROL END) BROKEN	
Action to correct:  REQUIRES A CONTROL END ROMAN BLIND MECHANISM  £85.00 VISA PAID	
Problem fixed on site: Yes/No	
Further action required: PLEASE SEND PART OUT BY POST TO:  DAVINPORT 38 ROWAN TREE AVENUE DURHAM DH1 1DU	