

C350255

HENDERSON/R

Fault Report

Customer Name: Henderson NEGS OHA	Date: 16.08.23
Customer Reference: 3502556 350255	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Venetians	
Fault Description: No hold down brackets sent for the lounge door.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Send some hold down brackets and book a service call to fit.	