

Fault Report

Customer Name: Porter	Date: 30.10.23
Customer Reference: 350521	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised venetians, All	
Fault Description: All blinds need AC/DC chargers and the remotes for the lounge and rear bedroom are not venetian remotes.	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Order 7 AC/DC chargers and 2 5 channel venetian remotes, all equipment for the temporary used batteries are in the unit.	

7 AC/DC chargers on del
31/10 - in clear poly bag
in unit