

G355341

SMYTH

② Fault Report

Customer Name: Date: Smyth 09-04-24

Customer Reference: Fitter: 355341

Salesperson: Salesperson called: Yes No

Blind Type and number:

Fault Description: OFFICE 3 + possibly 4.

1 / 2 blinds damaged

Action to correct:

re measure for blinds.

Problem fixed on site: Yes No

Further action required:

Customer needs 1 or 2 blinds to be re-made & charged.

Dave Needs to measure this as I am unsure on how to deduct sizes for the metro.

Can't use original sizes as wrong and Scott had to re order blinds.

* Sales app made *

Tuesday 30/4

Apologies i've had to go out at 3.15pm so likely will miss you. In the outbuilding there's an issue with the blind but it;s my fault. Basically the AC blows air and pushes the blinds against the window and i've opened the door without realising, hence twisting and damaging the blind. I've left the building open for you. Is it possible to salvage this and fix it or do i need to order a new blind? My number is 07813875475 and i can possible pop back depending on what time you arrive.

Cheers
Dan

45 The-grou

~~355341~~

355341

✓

Baileys

34 HIGH STREET,
SPENNYMOOR,
DURHAM DL16 6DB
TEL: 01388 813267 or 0191 258 5956
sales@baileys-blinds.co.uk
www.baileys-blinds.co.uk

Customer's Name SMYTH
Address 45, THE GROVE
GOSFORTH
Post Code NE31NH

Tel home
Tel work
mobile 07813 875475
email

DATE
MEASURED/ORDERED
5/12/23

Measured By:
DAVE

CURTAINS	
PLEATED	
ROLLERS	X10
ROMANS	
SHUTTERS	
VENETIAN	
VERTICALS	
VISION	
WOODEN	

SPECIAL INSTRUCTIONS
WHEN PROGRAMMING
THIS DROP PLEASE
STOP AT SKIRTING
BOARDS

2 MAN FIT WITH
A FRAMES 6 HOURS

PCUST	
NET	
PRESS	
RADIO	
MAG	
VAN	
RECC	
SHOP	
TV	
YELL P	
OTHER	

Fitted By _____ DATE _____ DAY _____ AM _____ PM _____

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top	brackets face
------	------------	-------	-------	------------	--------	--------	-------	-------------	-----------	----------	-----------	--------------	---------------

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Price
LIVING AREA	① 2130	3300	UNICOLOUR	TANNE + CAPS	1/2	3300	448.00
	② 2055	3300					448.00
	③ 2130	3300					448.00
	④ 1635	3300					380.00
	⑤ 1635	3150					380.00
	⑥ 2235	2790					407.00
	⑦ 2230	2790					407.00
	⑧ 2240	2790					407.00
	⑨ 2220	2790					407.00
	⑩ 1045	2875					232.00
				10x SONESSE ULTRA 30WF RTS ION	metal only		3340.00
				1 TELS 16 PURE, 5x V2 CHARCLES + 5x 2.4 EXT CABLES			394.00

21/12/21 - part fit + part payment by Bacs - see fault report SJ + DA.

* Service call 10/04/24 - fault report DA.

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. IF YOU REFUSE TO ALLOW A SAFETY DEVICE TO BE FITTED, THEN THE GOODS WILL NOT BE INSTALLED, AND UNDER THESE CIRCUMSTANCES YOU WILL STILL BE LIABLE TO PAY THE FULL PRICE UNDER YOUR CONTRACT. YOU ARE STILL BOUND TO ACCEPT DELIVERY OF THE GOODS AND TO PAY FOR BOTH THE FITTING AND INSTALLATION EVEN ALTHOUGH INSTALLATION HAS NOT BEEN CARRIED OUT.

FIT COMPLETED 18/10/24 SJ

I have ordered the above goods and agree to pay 50% deposit and the remaining balance on the day of fitting. If payment is not made in full at that time Baileys Blinds has the right to remove the goods until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE £7734.00
Pd 05/12/23 DEPOSIT £3867.00
Part Payment BALANCE £3867.00

PRICE ACCEPTANCE Customer's Signature
Autu 01/11/23
RATIBOW

CASH CHEQUE CARD

ALL BLINDS TO BE PAID FOR AT TIME OF FITTING

BBSA
BLINDS & SHUTTERS ASSOCIATION

Bacs £3,500.00 21/12/23.
[BAL £367.00] - Pd 19/01/27 Visa 077426

① Fault Report

Customer Name: Smyth	Date: 21.12.23
Customer Reference: 355341	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised rollers, Blind 4 & 5	
Fault Description: Blinds measured incorrectly.	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Blinds are in the unit to be collected and the size altered. Blind 5 should be 1595mm and blind 4 should be 1610mm.	

10FZ

MOTORIZED ROLLER BLINDS

Order Form

Special Instructions

Date: 5-12-23
Order Reference: 355341

Sales Rep: DAVE
Customer Name: SMYTH

Company/Shop: BAILEYS GOSFORTH

Location	BLIND SIZE & SYSTEM						CONTROLS						OPTIONS					
	Width (mm)	Drop (mm)	Recess (✓)	Exact (✓)	Child Safety Installation Height (mm)	System 12/40/45/ Berthin	Fabric Range	Fabric Colour	Motor Type	Remote Control	Slide RH / LH	Cassette Type & Colour	Roll	Finish	Bottom Bar	Bottom Bar End Caps		
1	2130	3300	✓		3300	40	UNICOLOUR	TAUPE	SONNENSEE ULTRA 30 WFR 15 10W		R	N/A						
2	2055	3300	✓		3300	40					R							
3	2130	3300	✓		3300	40					R							
4	1635	3300	✓		3300	40					R							
5	1635	3150	✓		3150	40					R							
6	2235	2790	✓		2790	40					R							
7	2230	2790	✓		2790	40					R							
8	2240	2790	✓		2790	40					R							

MOTOR EXTRAS/ACCESSORIES 1x TELS 16 PURE, 5x V2 CHARGERS + 5x 2.4 EXT CABLES /NOTES:

NOTE: UNLESS OTHERWISE STATED ALL MEASUREMENTS WILL BE TAKEN AS RECESS AND ALL OPTIONS WILL BE DEFAULT.

FITTING NOTES: