

Fault Report

| | |
|--|--|
| Customer Name: Ravel | Date: 29.11.23 |
| Customer Reference: 355240 | Fitter: Scott Johnson |
| Salesperson: Dave | Salesperson called: No |
| Blind Type and number: Roller, Con 5 | |
| Fault Description: Blind 5 measured incorrectly (too Small). | |
| Action to correct: N/A. | |
| Problem fixed on site: No | |
| Further action required: Remake Blind @2010mm recess. | |