

S356450

WALTON / R

Fault Report

Customer Name: Walton	Date: 13.11.23
Customer Reference: 356450	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Verticals, Lounge Bay	
Fault Description: incorrect size fabricated.	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Drop on Lounge Bay should be as measured. Remake vanes to correct drop.	