

ON100908R

5356469

WEBSTER /R

# Fault Report

Customer Name: Webster	Date: 21.12.23
Customer Reference: 356469	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Curtain pole	
Fault Description: the extra rings that were sent were the incorrect size	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Incorrect rings are in the unit, order correct rings for pole.	