

G355515

CARR/R

Fault Report

Customer Name: Carr	Date: 06.06.24
Customer Reference: 355515	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Shutters	
Fault Description: No tape for screw cover strips.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: 2 rolls of screw cover strip tape needed to complete the job. All shutters installed and caulked.	

