

G355836

HUMBLE / R

ON 101948R.

Fault Report

Customer Name: Date: Humble 07-06-24

Customer Reference: Fitter: 355836.

Salesperson: Salesperson called: Yes/No

DAVE

Blind Type and number:

Fault Description: H/R Rear bed.

H/R made wrong when open 1 side closes and other way when trying to close.

Action to correct:

re - make H/R.

Problem fixed on site: Yes/No

Further action required:

Please re make H/R + also make chain + tilt @ 550mm.