

Fault Report

ON 102412R

FITTER NAME: DAN	FITTING DATE: 29/7/24
Customer Name: HEMSWORTH	
Customer Ref: S357155	
Salesperson: SHAWN	Salesperson called: Yes/No
Blind Type and number: VERTICAL SLATS ONLY	
Problem fixed on site: Yes/No NO	
Fault Description SLATS ARE UPSIDE DOWN (DESIGN NOT SAME AS ROLLER BLINDS FITTED)	
Action to Correct:-	