

G356046
CURRY 12

Fault Report

FITTER NAME: Scott Johnson	FITTING DATE: 12.08.24
Customer Name: Curry	
Customer Ref: 356046	
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Wood venetian, Kitchen 1	
Problem fixed on site: Yes/No	
Fault Description: Blind is preventing the door from opening, See images in separate email.	
Action to Correct:- Remake the blind with a 35mm slat. Please discuss this with Graeme before actioning as he is going to check the headrail sizes first. Gap from wall to door is 52mm.	