

S357938
HARPER/R.

0N104162R

Fault Report

FITTER NAME: Scott Johnson	FITTING DATE: 17.03.25
Customer Name: Harper	
Customer Ref: 357938	
Salesperson: Shaun	Salesperson called: Yes/ <input checked="" type="checkbox"/> No
Blind Type and number: Curtain Pole, rear living room	
Problem fixed on site: Yes/ <input checked="" type="checkbox"/> No	
Fault Description: Incorrect pole length sent, 3m pole was sent needs to be 3380mm.	
Action to Correct:- Order new pole at the correct size.	



34 HIGH STREET,
SPENNYMOOR,
DURHAM DL16 6DB

TEL: 01388 813267 or 0191 258 5956

sales@baileys-blinds.co.uk

www.baileys-blinds.co.uk

Customer's Name **HARPER**

Address **19, CHRISTCHURCH CLOSE**

DARLINGTON

Post Code **DL1 2YL**

Tel. home	
Tel. work	
mobile	07801 706 594
email	

DATE
MEASURED/ORDERED
12/02/25

Measured By:
SHAUN HANLEY

SPECIAL INSTRUCTIONS
RWR

90

P/CUST	
NET	
PRESS	
RADIO	
MAG.	
VAN	
RECC.	
SHOP	
TV	
YELL P	
OTHER	

CURTAINS	
PLEATED	
ROLLERS	
ROMANS	
SHUTTERS	
VENETIAN	
VERTICALS	
VISION	
WOODEN	

Fitted By	DATE	DAY	AM	PM

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top	brackets face

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Price
* REAR LIV	3380	1370		PAIRS OF CURTAINS PIPER WOODSMOKE (C) LINED DOUBLE PINCH PLT			715
✓ G' FLOOR BED	2760	1340		B'OUT LINING			712
* LIV	3.38			CURTAIN POLE SATIN SILVER WITH STUD FINIALS 28MM WITH RINGS			138
✓ BED	2.76						114
							£1679
						LESS DISC 20%.	1343
				17/03/25 - part fitted - * see fault report			

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. IF YOU REFUSE TO ALLOW A SAFETY DEVICE TO BE FITTED, THEN THE GOODS WILL NOT BE INSTALLED, AND UNDER THESE CIRCUMSTANCES YOU WILL STILL BE LIABLE TO PAY THE FULL PRICE UNDER YOUR CONTRACT. YOU ARE STILL BOUND TO ACCEPT DELIVERY OF THE GOODS AND TO PAY FOR BOTH THE FITTING AND INSTALLATION EVEN ALTHOUGH INSTALLATION HAS NOT BEEN CARRIED OUT.

I have ordered the above goods and agree to pay 50% deposit and the remaining balance on the day of fitting. If payment is not made in full at that time Baileys Blinds has the right to remove the goods until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE	£ 1343
Pa 12/02/25 VISA 608080 DEPOSIT	£ 672
Pa 17/03/25 BALANCE VISA (PB)	£ 671

PRICE ACCEPTANCE Customer's Signature

Shaun Hanley

CASH	CHEQUE	CARD	✓
------	--------	------	---

ALL BLINDS TO BE PAID FOR AT TIME OF FITTING



Registered No.: 02814869

Baileys Blinds
 61 Canyon Road
 Excelsior Business Park
 Wishaw
 ML2 0EG



Curtain Fax Back Order form

Customer Name	HARPER
Customer Reference	357938

Date:	12-02-25
Date Required	

BAILEYS - 5' MOOR - SHAUN H

Curtain Ref	Single / Pair	No of Widths of POLE	Drop	Fabric Range & Colour (Also code if applicable eg. PR5111)	Fabric Supplier	Pattern repeat	Heading Type (Pinched Pleat, Double Pleat, Goblet, Standard)	Headed Size (For Pinched Pleat, Double Pleat and Goblet Headings)	Hook Position (Top / Middle / Bottom)	Lined / B/Out / Unlined	Lining Colour	Eyelet / Ring Colour (if req'd)	Tiebacks (YES / NO)	D/Ring and hook colour
	PAIR	3380	1370	PIPER WOODSMOKE	ARENA		DOUBLE			STD LINED	STD		NO	
	PAIR	2760	1340				PINCH PLEAT			R'OUT	STD		NO	

Special Instructions:

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Qty	Supplier	Width	Fitting Height	Pole or track description (Curtain Track / Cubicle Track / 1080 e)	Part Code	Brackets req?	Extras required (Hanger Rods / Fixing Kits etc)
1	ARENA	3.38		28mm SATIN SILVER			
1		2.76		POLE WITH STUD FINIALS AND RINGS			

Special Instructions:

--	--	--	--	--	--	--	--

Please state how curtains have been measured i.e from top of pole or from top to bottom of curtain.
 If Matching tiebacks are required, please state which colour of "D" ring required or if any piping required in the special instructions box.

*****Fitting height MUST be supplied for all tracks requiring cord or chain operating systems. If not supplied then cords/chains will be made as follows - Drop <2.5m Cord will be up to 1m long - Drop>2.5m Cord will be up to 1.5m long - This could result in you supplying a non-compliant product