

G361291

Fault Report

Customer AITCHINSON Name: Atkinson	Date: 18.02.26
Customer Reference: 361291	Fitter: Scott Johnson and Dan Adamson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Shutter, Diner Bay 3	
Fault Description: No cover strips in box	
Action to correct: Send cover strips.	