

Fault Report

Customer Name: Dunn	Date: 19.02.26
Customer Reference: 359284	Fitter: Scott Johnson
Salesperson: Shaun	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Shutter, Bay 1	
Fault Description: imperfection on door see images attached.	
Action to correct: Order new door to be fitted on site.	