

G 3601662

Fault Report

Customer Name: Ruddick	Date: 06.03.26
Customer Reference: 361662	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Roller, bedroom	
Fault Description: Roller should be in an anthracite 70mm cassette.	
Action to correct: Blind in unit for collection, to be resized and put in a cassette.	