

G 361641

Fault Report

Customer Name: Scullion	Date: 09.03.26
Customer Reference: 361641	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Wood Venetian bay 4, blind 4	
Fault Description: no right hand return on pelmet or return section.	
Action to correct: Order new pelmet with right hand return, also need a return and joining clip.	