

# Blinds Expert Order Report

Supplier	Network Blinds
Order No.	Hollingsworth ON4379
Date of Order	18-01-2024
Date Required	<del>08-02-2024</del>
Acc No.	

Invoice Details			
Name	Blinds Expert Ltd		
Address	1 MOOR VALLEY CLOSE		
	MOSBOROUGH		
	SHEFFIELD		
Postcode	S20 5DZ	Tel	0114 32 118 32

Delivery Details			
Name	Blinds Expert Ltd		
Address	1 MOOR VALLEY CLOSE		
	MOSBOROUGH		
	SHEFFIELD		
Postcode	S20 5DZ	Tel	0114 32 118 32

## VISION BLINDS

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	BATH	1085 mm	1140 mm	2300 mm	Left
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	NO				

**Net Cost: £60.18**

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	BACK BED	1625 mm	1135 mm	2300 mm	Right
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	NO				

**Net Cost: £94.73**

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	BAY A	460 mm	1405 mm	2300 mm	Left
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	YES				

**Net Cost: £66.42**

## Blinds Expert Order Report

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	BAY B	500 mm	1405 mm	2300 mm	Right
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	YES				
<b>Net Cost:</b>	<b>£66.42</b>					

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	BAY C	1650 mm	1405 mm	2300 mm	Right
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	YES				
<b>Net Cost:</b>	<b>£117.67</b>					

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	KIT A	1310 mm	1155 mm	2400 mm	Right
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	NO				
<b>Net Cost:</b>	<b>£88.05</b>					

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	KIT B	895 mm	850 mm	2400 mm	Right
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	NO				
<b>Net Cost:</b>	<b>£53.50</b>					

# Blinds Expert Order Report

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	DOWN BAY A	640 mm	1405 mm	2400 mm	Left
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	YES				
<b>Net Cost: £69.77</b>						

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	DOWN BAY B	490 mm	1405 mm	2400 mm	Right
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	YES				
<b>Net Cost: £66.42</b>						

Qty	Blind or Recess	Room	Width	Drop	Fitting Height	Control Side
1	Blind	DOWN BAY C	1645 mm	1405 mm	2400 mm	Right
Child Safety	Cord Tidy	Pricing Band	Fabric	Colours	Hardware Colour	Fabric insert
Yes	Side Fix Cord Tidy	Group B	Setosa	White	White	Yes
Brackets	Chain Type	Pattern Match				
Top Fix	Metal Cont	YES				
<b>Net Cost: £117.67</b>						

**Total Net Cost: £800.83**